

PERFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION
CERTIFICATE

NO. 398.....

DATE 29/04/2024.....

It is certified that an inspection team headed by Er. Shubash Singh junior Engineer and Sri Dharmendra kumar, Lab Assistant (Name of officers with designation) from Public Health Sub Division , Laheriasarai Darbhanga (Name of Department / office) inspected the Holy Mary International School , Bahadurpur Chintamanpur, Pandasarai, Thalwara Road, Laheriasarai, Darbhanga (Name & Address of the School) on 25.04.2024 (Date of inspection) has safe drinking water Facilities for the students and members of staff of the Institution and is maintaining the hygienic sanitation condition in the school building & the campus as per the norms prescribed by the Central/ State/ U.T Govt.

The above valid for a period of one Year

Signature with seal.....
Name :- Er. Sudhanshu Shekhar Chaurbey
Designation :- Assistant Engineer
Name & Address of the office/ Department:-
P.H Sub Division , Laheriasarai Darbhanga

To


Principal,

Holy Mary International School,

Bahadurpur Chintamanpur, Pandasarai,

Thalwara Road, Laheriasarai, Darbhanga.

Pin Code- 846001


Dr Shibu V. Rana
Principal
Holy Mary International School
Up to Senior Secondary Level
Pandasarai, Laheriasarai
Darbhanga-846001


MANAGER / M. D.
HOLY MARY INTERNATIONAL SCHOOL
LAHERIASARAI, DARBHANGA